



*Holy Cross Church with existing fellowship hall (right)*



*Holy Cross Church from existing entrance on Craigs Store Road*



*View from existing entrance looking northeast along Craigs Store Road*



*Bank along Craigs Store Road at location of proposed new entrance (see stakes), showing initial steep slope and rise to elevation of existing driveway (see truck at top left).*